
Canvas
Instruction Manual


Not included:
CAT 5e/6/7 Ethernet cable
4 screws suitable for your wall type (5 mm diameter, or #10 screw)
Whiteboard up to 2 m x 1.2 m/6' x 4'



Place the wall bracket 14 cm/5.5" above the center of your whiteboard

Mount the wall bracket with the tabs facing out


Secure the wall bracket using four screws suitable for your wall type




Rotate the camera arm so that it points down

Fasten the Canvas camera with the camera screw


Connect the USB cable to the camera



Place the Canvas housing over the wall bracket and slide it down carefully until it is safely in place




Connect your Ethernet cable to the top of the Canvas housing



Connect the other side of the Ethernet cable to the included USB extender

Use the included USB cable to connect the USB extender to your meeting room computer

Connect the AC Power Adapter to the USB extender and a power socket



To finish the installation, visit **huddly.com/canvas/setup**

Huddly